





1119



2/19




Figure 1E




Figure 1F

3/19

16 ↗

↗ 16




Figure 2A

Figure 2B




Fig. 2C

Fig. 2D

4/19

Fig. 3A




Fig. 3B





Fig. 3C



519




figure 4

6/19




Fig. 5A




Fig. 9A )

7/19




Fig 5B

8/19




Figure 6

9/19




Fig. 7




Figure 8A

11/19




Figure 8B

12/19





Figure 9B






Figure 10C

15119





FIG. 10D

16119



Foot Stirrup  
w/ Connecting Ring

Figure 11

17119




FIG. 13A





FIG. 12



19 | 19




Figure 14